

整流器 CHUCK CONTROLLER

GD-201-5A TYPE G905-5A TYPE

- 電壓為 AC110V或220V 容量為5A。
- DC由10V~100V可自由調整其電壓，由數字(LED)顯示，故很容易找到所需之電壓。
- 具有IC消磁裝置，消磁時間6秒至10秒。
- 加工物在磁盤之磁場範圍內方便加工物取下。
- 附有固定板，可固定在容易操作的位置。
- GD-201-5A備有同步吸磁接點可和機械之控制器配合，使機械只有在吸磁時才會動作，以提高安全性。
- AC/110V or AC/220V Capacity is 5A.
- DC 10V~100V adjustable, digital (LED) display, easy to set up.
- With IC demagnetize installation, demagnetized time is 6sec.-10sec.
- When the workpiece is in the range of magnetic field of magnetic chucks, the workpiece with the magnetic field of the magnetic chuck can be removed conveniently.
- Attachment of fixed plate, can be conveniently fixed at the desired
- GD-201-5A The synchronous charge contact works the mechanical controller so that the machine operates only when charge is activated to ensure the safety of the operator.



GD-201-5A



G905

單位: mm

型號 Model	輸 入 Input Voltage		輸 出 Output		尺 寸 Dimension (mm)			淨 重 NET Weight
	(Single Phase)		Voltage	Current	L	W	H	(KG)
GD-201-5A	1.	AC 110V	DC 10V~100V	5A	200	135	125	3.2 kg
	2.	AC 220V						
G905-5A	1.	AC 110V				137	122	3.5 kg
	2.	AC 220V						

* 型錄上產品規格尺寸僅供參考，以本公司實際產品為主為準，變更時恕不另行通知。

The specifications and dimensions of products in the catalogs are for reference only. Subject to be changed without any notice.

整流器 CHUCK CONTROLLER

GD-3 TYPE

- 電壓多重選擇依客戶地區訂製，容量10A至20A以上可選擇。
- DC輸出由DC 6V~100V，分10段調整，LED燈號正確快速找到所需之電壓。另有DC110V~200V以上的特殊壓可以訂製。
- 具有消磁功能，消磁時間6秒內。讓加工物在磁盤之磁場範圍內方便加工物取下。
- 備有同步吸磁接點可和機械之控制器配合，使機械只有在吸磁時才會動作，以提高安全性。
- 大型的整流器也可配合電磁盤的數量訂製一台總控制器，可多重組合10A×N或15A×N台，一次操作，省下分台分次的操作時間。
- The Input voltage (AC) can be customized upon request, and the current capacity is from 10A to 20A UP.
- The standard output voltage is from DC 6V~100V in 10 stages adjustment. It is fast and easy to find the correct and required voltage by the LED signal. Special voltage of DC110V~200V can be customized.
- With demagnetizing function, the demagnetized time is within 6 seconds. It is convenient to remove the workpiece from the magnetic chuck in the range of magnetic field of magnetic chuck.
- The synchronous charge contact can connect with the machine controller. To ensure operator safety, only when the charge is activated then the machine work
- According to the numbers of electromagnetic chucks, the main controller can be customized and it is multiple combinations of 10A×N or 15A×N units in one large control box. The one operation can save the time of operating the individual controller.

單位: mm

型號 Model	輸 入 Input Voltage		輸 出 Output		尺 寸 Dimension (mm)			淨 重 NET Weight
	(Single Phase)		Voltage	Current	L	W	H	(KG)
GD-310A	1	AC110/220V	1.標準 Standard DC 6V-100V	10A	150	330	260	17KG
	2	AC 220/380V		12A				20KG
	3	OTHER						
GD-312A	1	AC110/220V	2.訂製 Customization DC110V ~ DC 200V	12A	150	330	260	20KG
	2	AC 220/380V						
	3	OTHER						
GD-315A	1	AC 220V	2.訂製 Customization DC110V ~ DC 200V	15A	150	330	260	24KG
	2	AC 380V						
	3	OTHER						
GD-3 20A UP		AC 220V~AC440V		20A以上可接受訂製 20A UP CUSTOMIZATION				

* 型錄上產品規格尺寸僅供參考，以本公司實際產品為主為準，變更時恕不另行通知。

The specifications and dimensions of products in the catalogs are for reference only. Subject to be changed without any notice.